Location NE 1/4 NW 1/4 Sec 32 Twp 168 Rg 61	Well Owner:	
County North		
Dontin X	Address: 1752 hc	Ponds Dr
Please mark well location with an "X"	- Huron S.D.	52350
	WELL LOG: DEPTH	
W E	FORMATION	FROM TO
	holler Dan	0 20
Well Completion Date	Blue	20 50
11/0/00	Comment of the commen	50 75
	of of	
LOCATION:	- Blue Clay	75
Distance from nearest potential pollution source (septic tank, abandoned well,		
feed lot, etc.)? 120 ft. from Septin Land (identify source).		
PROPOSED USE:	]	
Domestic/Stock  Municipal  Business  Test Holes		
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well		
METHOD OF DRILLING:	STATIC WATER LEVEL 46	
Kotary	1	
CASING DATA: Steel Plastic Other	If flowing: closed in pressure GPM flow through	
If other describe	Controlled by Valve Reducers Other	
PIPEWEIGHT DIAMETER FROM TO HOLE DIAMETER	Reduced Flowrate	·
LB/FT <u>5</u> in <u>6</u> ft <u>666</u> ft <u>8 34</u> in	Can well be completely shut in?	
LB/FTINFTFTIN		
LB/FTINFTFTIN	WELL TEST DATA:  Pumped Describe: 75	IR mes.
GROUTING DATA	□ Bailed □ Scribe: □ Co	maren 1
Grout Type No. of Sacks Grout Weight From To	Other	70
1 delny 3 16./gal 20 ft 60 ft	Pumping Level Below Land Surface	
Describe grouting procedure	ft. AfterHrs. pumped	GPM
line to 61 xt.	ft. AfterHrs. pumped	A SOLUTION
SCREEN: Perforated pipe Manufactured		AUG 1999  WATER RIGHTS TO
DiameterIN LengthFEET MaterialFORTH	\ <u>\</u>	DDOCE ALL W
Slot Size Set From 66 Feet to 77 Feet		Pierre, SD
Other information		Pierre, SD OF
Grand Rocked	0/11	
	This well was difficultified filedisc if	3
WAS A PACKER OR SEAL USED? YES NO	And this report is true and accurate.  Drilling firm Julian Level	1 Pr. Ol.
If so, what material?		1 7404
Describe packer(s) and location?	Signature of License Representative:	
DISINFECTION: Was well disinfected upon completion?  YES, How:	K. Stuck	
aboratory sent to for waterNO, Why Not?	Signature of Well Owner or Equitable Property Holder:	
uality analysis	, <del></del>	
	Date:	
		9/3/99
	and the second s	